


IMG_4302: More severe fire damage noted at soffit framing.




IMG_4303: Roof deck severely damaged.




IMG_4304: Severely damaged trusses & roof deck.



IMG_4305: Severely damaged trusses & roof deck.



IMG_4306: Severe damage to trusses & deck.



IMG_4307: Sever damage to trusses & deck.



IMG_4308: Overview of interior damage.



IMG_4309: Stucco finish broken away at roof tie beam. Concrete beam extends over window.




IMG_4310: Units #39 & #40



IMG_4311:



IMG_4312:



IMG_4313:




IMG_4314:



IMG_4315:



IMG_4316:



IMG_4317:



IMG_4318: Moderate damage to trusses and decking at this location.



IMG_4319:




IMG_4320:




IMG_4321:



IMG_4322:



IMG_4323: Severe truss and deck damage at this location.



IMG_4324: Severe damage to trusses & deck.



IMG_4325: Severe damage to trusses & deck.



IMG_4326:



: